

Inspection Photos

API: 05-071-06716

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Facing southwest toward the recontoured and reclaimed road.

Inspection Photos



Photo 2. There is little vegetation establishing at the beginning of the reclaimed road. This area may require additional seeding.

Inspection Photos



Photo 3. Rock rip/rap is placed in the drainage channel.

Inspection Photos



Photo 4. Facing back toward the northeast.

Inspection Photos



Photo 5. Facing southwest along the recontoured and reclaimed road.

Inspection Photos



Photo 6. There are signs vegetation is beginning to establish.