

Inspection Photos
Operator: Ausco Petroleum Inc.
Location/API #: 043-06226
Date: 2/27/2019



Photo 1. View of the project area from the northeastern corner facing center. Project area appears recently reclaimed.



Photo 2. View of the northern portion of the project area from the northeastern edge facing southward. Fencing is not functioning and needs to be repaired or removed. Livestock/wildlife exclusion may be needed for successful revegetation.



Photo 3. View of debris around well head area. Well cellar should be properly closed to prevent wildlife entrapment.



Photo 4. View of the southern project area from the southeastern edge facing westward. Area appears to be recently reclaimed.



Photo 5. View of plastic netting debris that needs to be removed.



Photo 6. View of wattle debris in the southeastern project area. .