

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

687903865**FIELD INSPECTION FORM**Loc ID 326584 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258298	WELL	PR	05/07/2001	GW	067-08350	ALLISON UNIT 147	PR

**General Comment:**[Downloadable photos at the end of this inspection report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Clay dirt road access.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign located on fence at tank battery.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: correct emergency contact information. (505) 324-5170

Corrective Action:  Date: Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	T-post and hogwire fence around produced water tanks.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 258298 Type: WELL API Number: 067-08350 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing.](#)

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903866	Location Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755714</a>
687903867	Sep. and Meter Run	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755715</a>
687903868	Pump Jack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755716</a>