

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

696100402

FIELD INSPECTION FORM

Loc ID 306743 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Barbula, Don		dbarbula@bayswater.us	all inspections
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290643	WELL	SI	10/01/2018	OW	123-25183	HESTER 31-23	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** Inspection.
Centralized Battery presently exists & serves 4 Location IDs (306151, 305997, 309702, 310194).
Centralized Battery formerly served this P&A well Location ID (306743).
Refer to FIR #696100064 and/or Location ID #306151 for Battery / Facility, Equipment info.
Well is PA.
Battery & ALL equipment is Shut-down.
Follow-up to FIR #696100072 dated 02/06/2019.
1 of 1 Corrective Actions has been addressed.
1.) Casing was NOT cut & capped and remained open ended presenting a potential safety hazard.
Observed well appears cut & capped below ground level. Wellsite reclamation in process. See photos #1-2.

[No Corrective Actions identified on this FIR.](#)

Inspected Facilities

Facility ID: 290643 Type: WELL API Number: 123-25183 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: From prev. FIR. Casing had NOT been cutoff & capped. No temporary safety casing cap was installed.
 Casing remained exposed approximately 18" above ground surface.
 Cement did NOT appear inside of open casing.
 Currently observed well appears cut & capped below ground surface. Wellsite reclamation in process. See photos #1-2.
 Form 6 #401940393 indicated plugging date: 12/19/2018. (Approval Pending).

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100404	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755900