

Inspection Photos
Operator: Ausco Petroleum Inc.
Location/API #: 043-06230
Date: 2/27/2019



Photo 1. View of the project area from the southern edge facing northward. Project area appears recently reclaimed.



Photo 2. Birdseye view of reclamation within the project area. Small, green grass seedlings are observable within straw mulch.



Photo 3. View of the western portion of the project area from the southern edge facing westward.



Photo 4. View of the eastern project area from the southern edge facing eastward.



Photo 5. View of swale in the northern project area where snow melt is causing erosion. Stormwater controls are needed to stabilize erosion and sediment run-off from the project area.



Photo 6. View of headcut erosion within and upstream from the drainage in Photo 4. Stormwater controls are needed to stabilize erosion here.