

# Construction and Stormwater Inspection

February 28, 2019

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 444377

Inspection Document #: 682404596

Weld County, CO

SWSE Section 28 T12N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Fox Creek /28 SWSE  
Location ID: 444377



**Photo 1.** Photo taken from the southeastern perimeter of location, facing North. Photo illustrates a ditch and wattle BMP. The ditch does not appear to be constructed to a sufficient depth and wattle BMPs have not be staked.



**Photo 2.** Photo taken from the northeastern perimeter of location, facing West. Photo illustrates the topsoil stockpile. Based on field observations and calculations, Operator has not salvaged the required amount of topsoil. Operator shall properly stabilize the topsoil stockpile per Rule 1002.c.



Inspection Photos  
Location Name: Fox Creek /28 SWSE  
Location ID: 444377



**Photo 3.** Photo taken from the northern perimeter of location, facing Southwest. See comments under Photo 2.



**Photo 4.** Photo taken from the western perimeter of location, facing South. Photo illustrates unconsolidated soil material that shall be stabilized, as this is susceptible to wind and water erosion.



Inspection Photos  
Location Name: Fox Creek /28 SWSE  
Location ID: 444377



**Photo 5.** Photo taken from the southwestern perimeter of location, facing South. See comments under Photo 4.



**Photo 6.** Photo taken from the southwestern perimeter of location, facing East. Photo illustrates unconsolidated soil material that shall be stabilized and wattle BMP that has not be staked.

Inspection Photos  
Location Name: Fox Creek /28 SWSE  
Location ID: 444377



**Photo 7.** Photo taken from the southeastern perimeter of location, facing East. Photo illustrates Operator is using topsoil to create a berm BMP. See comments under Photo 6.