

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2019

Submitted Date:

03/08/2019

Document Number:

688800479**FIELD INSPECTION FORM**
 Loc ID 313482 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	SW Inspection Reports
Jardine, Jennifer		jjardine@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112977	PIT	AC			-	SCHMIDT 2	EI
224191	WELL	PR	11/30/2007	GW	083-06256	SCHMIDT 2	EI

General Comment:

On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Schmidt #2. For the most recent field inspection report of this facility, please refer to document #688800351. Pit Facility ID #112977 has been returned to service.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near well head.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	Tanks have placards and are labeled with contents and capacity. Label on tank next to wellhead is peeling off. Temporary tanks are no longer in use, Pit Facility ID #112977 is in use.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	New emergency contact number has been installed on location sign. Number verified as a 24/7 manned hotline.			
Corrective Action:				Date:
Good Housekeeping:				
Type	TRASH			
Comment:	Used liner piled up along east side of access road, north of production equipment.			
Corrective Action:	Comply with Rule 603.f.		Date:	04/08/2019
Type	UNUSED EQUIPMENT			
Comment:	Remove ~900 gallon fiberglass tanks used while pit upgrades took place.			
Corrective Action:	Comply with Rule 603.f		Date:	06/10/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Steel pipe protective barricade around wellhead.			
Corrective Action:			Date:	
Equipment:				
Type: Flow Line	# 2		corrective date	
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			

Comment: Combustor		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Telemetry equipment.		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 2	
Comment:		
Corrective Action:		Date:
Type: VRT	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<50 BBLs	FIBERGLASS AST		,
Comment: Two ~900 gallon fiberglass ASTs were in use until pit #112977 was put back into service. Remove unused equipment from location.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	900 gal.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Poly temporary secondary containment for produced water tanks.				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	112977	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI	
Facility ID:	224191	Type:	WELL	API Number:	083-06256	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 112977Lat: 37.364793Long: -108.787530Reference Point: SEOther: Length: Width: **Lining:**Liner Type: PlasticLiner Condition: AdequateComment: Corrective Action: Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YESComment: Ensure slopes within construction area are properly stabilized. Settling cracks observed during this inspection along north and west sides of pit.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Schmidt #2. For the most recent field inspection report of this facility, please refer to document #688800351. Pit Facility ID #112977 has been returned to service. 2 fiberglass ASTs used while pit upgrades and remediation took place, are no longer in use. Pit Facility ID #112977 is fenced and netted. Equipment blew down to pit several times during this inspection. Ensure that mist generated during blow down does not migrate outside of pit area. Recently constructed slopes along the north and west sides of the pit area have settling cracks in the soil. Ensure slopes are stabilized and compacted.	hughesjo	03/08/2019

Attached Documents

Inspector Name: Hughes, Jim

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800480	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757233