

Inspection Photos
Operator: Javernick Oil
Location/API #: 043-06124
Date: 2/27/2019



Photo 1. View of the project area from the southwestern edge facing center. Revegetation is progressing within the interim reclamation areas.



Photo 2. View of the southern project area from the southwestern edge facing eastward.



Photo 3. View of area within the southeastern project area where an erosional channel is forming and stormwater controls are needed.



Photo 4. View of tank battery location south of the well pad.