

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 0		
Comment:			
Corrective Action:		Date:	
Horizontal Separator	# 0		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 0		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 270293 Type: WELL API Number: 123-21858 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This is a follow up inspection per Doc#69120177. All corrective actions have been addressed at time of inspection. MIT was preformed on 02/26/2019. Form 21 Doc #401958430 has been submitted to the COGCC for review.	petrie	03/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300009	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757325