

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2019

Submitted Date:

03/08/2019

Document Number:

689303474

FIELD INSPECTION FORMLoc ID 335451 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: VANGUARD OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275784	WELL	PR	04/03/2006	GW	045-10384	EPPERLY 14C-23-692	AC
275867	WELL	PR	04/05/2006	GW	045-10390	EPPERLY 24C-23-692	AC
276459	WELL	PR	06/01/2013	GW	045-10463	EPPERLY 24A-23-692	AC
276461	WELL	PR	04/01/2006	GW	045-10464	EPPERLY 14A-23-692	AC

General Comment:

This is a follow up inspection from Doc# 689303392. Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	275784	Type:	WELL	API Number:	045-10384	Status:	PR	Insp. Status:	AC
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	275867	Type:	WELL	API Number:	045-10390	Status:	PR	Insp. Status:	AC
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	276459	Type:	WELL	API Number:	045-10463	Status:	PR	Insp. Status:	AC
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	276461	Type:	WELL	API Number:	045-10464	Status:	PR	Insp. Status:	AC
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						Location is muddy
		Gravel				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303475	Inspection photo 689303475	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757350