

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2019

Submitted Date:

03/08/2019

Document Number:

689303484

FIELD INSPECTION FORM

Loc ID 335442 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------|------------------------|
| Aaron, Axelson | 230-0926 | aaxelson@vnrenergy.com | Sr. Production Foreman |
| Ghan, Scott | 970-744-8128 | sghan@vnrenergy.com | SR. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 282722 | WELL | PR | 10/14/2009 | GW | 045-11801 | BBC 42C-23-692 | PR |
| 282723 | WELL | PR | 10/13/2009 | GW | 045-11800 | BBC 42A-23-692 | AC |
| 282724 | WELL | PR | 09/24/2009 | GW | 045-11799 | BBC 12B-24-692 | AC |
| 282726 | WELL | PR | 09/22/2009 | GW | 045-11798 | BBC 13D-24-692 | PR |
| 282728 | WELL | PR | 09/22/2009 | GW | 045-11797 | BBC 12D-24-692 | PR |
| 299502 | WELL | PR | 09/24/2009 | GW | 045-17688 | BBC 12C-24-692 | PR |
| 299503 | WELL | PR | 04/17/2012 | GW | 045-17689 | BBC 42B-23-692 | AC |
| 299504 | WELL | PR | 09/30/2009 | GW | 045-17690 | BBC 12A-24-692 | AC |
| 299505 | WELL | PR | 10/02/2009 | GW | 045-17691 | BBC 42D-23-692 | PR |

General Comment:

This is a follow up inspection from Doc#689303402 . Required Corrective Action (s) items noted in previous inspections have been satisfied.
Equipment inventory has not changed on location.

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 282722 | Type: | WELL | API Number: | 045-11801 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 282723 | Type: | WELL | API Number: | 045-11800 | Status: | PR | Insp. Status: | AC |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 282724 | Type: | WELL | API Number: | 045-11799 | Status: | PR | Insp. Status: | AC |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 282726 | Type: | WELL | API Number: | 045-11798 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 282728 | Type: | WELL | API Number: | 045-11797 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 299502 | Type: | WELL | API Number: | 045-17688 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 299503 | Type: | WELL | API Number: | 045-17689 | Status: | PR | Insp. Status: | AC |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 299504 | Type: | WELL | API Number: | 045-17690 | Status: | PR | Insp. Status: | AC |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Producing Well

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 299505 Type: WELL API Number: 045-17691 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Rip Rap | | | | | | |
| Berms | | | | | | |
| Gravel | | | | | | |
| | | Ditches | | | | |
| | | Sediment Traps | | | | |
| | | Gravel | | | | |
| Compaction | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689303485 | Inspection photo 689303485 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757355 |