

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2019

Submitted Date:

03/04/2019

Document Number:

687903773

FIELD INSPECTION FORM

Loc ID 311887 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
 Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
 Address: 1801 BROADWAY #1000
 City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216304	WELL	PR	07/01/2011	GW	067-07910	F W TERRELL GAS UNIT 2	PR
296161	WELL	PR	06/19/2018	GW	067-09559	IGW 122	PR

General Comment:

This is a follow up inspection regarding document# 687903677. [Downloadable photos at end of report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Metal framed sign at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact information current. (970) 442-6620	Date:	
Corrective Action:			

Good Housekeeping:

Type	TRASH		
Comment:	oily rags and used parts on pump jack skid have been cleaned up to comply with Rule 603.f.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Metal building with unused equipment.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f. Allowing extra time to comply with CA due to weather conditions and time of year.	Date:	05/30/2019

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		,
Comment:	Repaired leaking valve and installed bull plug in IGW 122 produced water tank to comply with Rule 605.d.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Tires/trash have been removed from secondary containment to comply with Rule 603.f.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 216304 Type: WELL API Number: 067-07910 Status: PR Insp. Status: PRFacility ID: 296161 Type: WELL API Number: 067-09559 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

This is a follow up inspection regarding document# 687903677. Some CA's have not been completed due to adverse weather conditions and CA time allotted not being reached, therefore, follow up inspection still required.

stewartj

03/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401959374	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751985
687903775	oily rags/parts picked up	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751980
687903776	unused equipment still currently on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751981
687903777	Valve replace and tires/trash removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751982