

Inspection Photos
Operator: Ausco Petroleum Inc.
Location/API #: 043-06219
Date: 2/28/2019



Photo 1. View of the project area from the eastern project area facing center toward the well.



Photo 2. View of the eastern project area from the eastern corner facing southward. Wattles are placed around the perimeter of the project area.



Photo 3. View of the northern project area from the eastern corner facing northwestward.



Photo 4. View of area around water truck where it appears that drilling fluids have been released.



Photo 5. View of area downslope from well and water truck where salt crust and mud may indicate release of drilling fluids flowing downslope from the project area.



Photo 6. View of area near the access entrance where wattle installation is not completed.



Photo 7. View of area along access where run-on controls and stabilization are needed. Additional areas along access where stormwater needs to be managed and controlled remain.