

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2019

Submitted Date:

03/11/2019

Document Number:

694400103

FIELD INSPECTION FORM

Loc ID 318529 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16910
Name of Operator: CHURCHILL ENERGY INC
Address: 8177 SOUTH NORFOLK STREET
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
Pesicka, Conor		conor.pesicka@state.co.us	
Carroll, Kathy	(303) 987-0241	kc2121@prodigy.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241510	WELL	PR	04/01/2018	GW	123-09299	STROMBERGER UNIT 2-12	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment: Signage at battery has incorrect or non working contact numbers. See Photo# 4

Corrective Action: Install sign to comply with 210.b

Date: 02/11/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other	# 1		corrective date
-------------	-----	--	-----------------

Comment: Wellhead master valve appears to be broken. See Photo #3

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/11/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,

Comment: Crude oil tank load out valve has developed a leak. See photo #2

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/11/2019

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:

Corrective Action:

Date:

Venting:

Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>

Flaring:

Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>

Inspected Facilities

Facility ID: 241510 Type: WELL API Number: 123-09299 Status: PR Insp. Status: PR

Producing Well

Comment: On Monday March 11th I, Adam Kraich, Performed an inspection of the Stromberger 2-12 well and location. Location ID 318529. Well API# 123-09299.
 This is a follow up inspection to document #674301438
 At time of inspection, I observed the following conditions:
 Leaking load line valve on production tank. See Photo #1. Citing 605.d
 Appears to be a broken master valve on wellhead. See photo #2. Citing 605.d
 Signage emergency contact information is not accurate. See photo #3, Citing 210.b
 No corrections have been made in regard to the aforementioned issues.
 END.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400104	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759509