



**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SIGN ON METER HOUSE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Type: Other		# 1		
Comment:	BREADENHEAD IS PLUMBED TO SURFACE			
Corrective Action:			Date:	
Type: Gas Meter Run		# 1		
Comment:	No calibration records present in meter house			
Corrective Action:			Date:	
Type: Ancillary equipment		# 1		
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 263018 Type: WELL API Number: 071-07600 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP INPSECTION TO INSP. DOC#688400203. IT DOES NOT APPEAR THAT THE CORRECTIVE ACTION WAS COMPLETED. i WAS UNABLE TO FIND THE CALIBRATION REPORT IN METER HOUSE.	beardsit	03/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100342	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759522">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759522</a>