


Inspection Photo (s)
Clough RMV 27-28
API # 05-045-06958
FIR Inspection # 689303496



Location Photo #1

Location Photo #2