

Inspection Photo (s)
Clough 128
API # 05-045-06384
FIR Inspection # 689303498



Location Photo #1



Location Photo #2

Inspection Photo (s)
Clough 128
API # 05-045-06384
FIR Inspection # 689303498



**Location Photo #3, unmarked flow line riser
near meter run.**