

Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
FIR Inspection # 689303500



Location Photo #1



Location Photo #2

Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
FIR Inspection # 689303500



Location Photo #3, unmarked flowline.



Location Photo #4, Debris behind the separators.

**Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
FIR Inspection # 689303500**



Location Photo #5, Debris west of separators.



Location Photo #6, Debris west of separators.