

Inspection Photos
Operator: Javernick Oil
Location/API #: 043-40024
Date: 2/28/2019



Photo 1. View of the northern project area from the northwestern edge facing toward the wellhead. Wellhead is adjacent to an erosion channel. This area needs immediate stabilization to prevent any further erosion.



Photo 2. View of the project area from the southeastern corner facing northwestward. Revegetation within the teardrop and outer revegetation areas is progressing.



Photo 3. View of the project area from the southeastern project area facing northeastward from the southeastern edge.