

Inspection Photos

Operator: Javernick Oil
Location/API #: 043-40012
Date: 2/28/2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern edge facing southward. Vegetation on the slope is sparse and needs stabilization. Metal cable debris is present. Loose soil on edge is insufficient to function as berm.



Photo 3. View of more cable and wood debris within the northeastern project area.



Photo 4. View of area where pipe daylights on eastern slope.



Photo 5. View of teardrop area that is weedy with poor revegetation.