

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2019

Submitted Date:

03/12/2019

Document Number:

696300014

FIELD INSPECTION FORM

Loc ID 418911 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426013	TANK BATTERY	AC	08/24/2010		-	LARSON TANK BATTERY	AC

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Stained soil by load line bucket, see photo 3

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 04/12/2019

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: Automation RTU at gas meter

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		

Comment: Large hole drilled in water tank, see photo #2

Corrective Action: Install or repair wildlife protection equipment

Date: 04/12/2019

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with production tanks.					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		40.562740,-104.795890
Comment:					
Corrective Action:				Date:	

<u>Paint</u>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms could use maintenance in the near future. Shares berms with water tank					
Corrective Action:				Date:	

<u>Venting:</u>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>	
Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 426013 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>On 3/12/2019, I Erica Petrie performed an inspection of the Larson Tank Battery (location ID 418911) wellhead, owned and operated by Great Western Oil & Gas.</p> <p>While on inspection I observed the following issue(s) Hole cut in water tank, see photo #2, Cite 324A.a Stained soil present at load line bucket, see photo #3, Cite 605.d END.</p>	petrie	03/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300015	Tank Battery Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4760328