

Inspection Photos
Operator: Javernick Oil
Location/API #: 043-40025
Date: 2/28/2019



Photo 1. View of the project area from the northern edge facing southeastward. Project area and secondary road are not reclaimed.



Photo 2. View of the western project area from the norther edge facing southwestward. Secondary road needs to be reclaimed along with the production area.



Photo 3. View of the eastern project area from the northern edge facing eastward.



Photo 4. View of area within the northeastern project area where erosional channel is forming due to concentrated stormwater flows.



Photo 5. View of metal debris and darkened soils that may indicate stained soils from historic release.



Photo 6. View of more debris within the project area.