

Inspection Photos

3/08/2019

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 447898

Inspection Doc. Number: 682504588

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the ditch along the eastern perimeter of the location. Areas of the stormwater ditch appears to have filled with sediment. Advise maintenance.



Photo 2: Velocity checks within stormwater ditch. Erosion degradation at soil stockpile.



Photo 3: Photo taken from the northeast corner of the location, facing west. Photo shows erosion degradation on the soil stockpile.



Photo 4: See comments under photo 3.



Photo 5: Photo taken from northeast corner of the sediment trap.



Photo 6: Photo taken from northwest corner of the sediment trap. Photo shows insufficient inlet protection. Gully erosion evident at trap.



Photo 7: See comments under photo 6



Photo 8: Photo taken from southwest corner of the sediment trap. Photo shows inlet is filling with sediment. Advise maintenance.



Photo 9: See comments under photo 8.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 447898



Photo 10: Photo taken from topsoil stockpile on the east end of the location. Photo shows stormwater degradation becoming evident.



Photo 11: See comments under photo 10.



Photo 12: See comments under photo 3.