

Inspection Photos

API: 05-025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 3/11/2019

Inspection Photos



Photo 1. Facing northwest at the location. Two drilling pits remain. The location has not been recontoured and reclaimed.

Inspection Photos



Photo 2. Pit liner remains in the south pit. The liner is torn and not maintained.

Inspection Photos



Photo 3. The north pit is full of water. Water will need to be pump out and drained.

Inspection Photos



Photo 4. Facing southwest toward the location. The ditches directed toward the pit will need to be filled in and reclaimed (Yellow arrow). The ditch at the eastern perimeter (red arrow) can remain.

Inspection Photos



Photo 5. Plastic trash debris needs to be removed.

Inspection Photos



Photo 6. The northern ditch needs to be filled in and reclaimed.

Inspection Photos



Photo 7. There very little vegetation establishment at the location. Soil is susceptible to erosion.

Inspection Photos



Photo 8. There very little vegetation establishment at the location. Soil is susceptible to erosion. There are weeds throughout the location.