

Inspection Photos
Operator: Javernick Oil
Location/API #: 043-06059
Date: 2/28/2019



Photo 1. View of the access road from the beginning of the road facing upslope toward the well pad. Access road is not reclaimed.



Photo 2. View of erosional headcut approximately 3-4 feet wide and deep along the access road that needs to be reclaimed.



Photo 3. View of the project area from the northern corner facing center. Revegetation with desirable species is present within portions of the former well pad area.



Photo 4. View of area approximately 10 feet wide and 20 feet long on the former well pad area, where vegetation is not becoming established. This area likely needs additional decompaction, soil testing, and amendments (as determined during soil testing) for successful revegetation.