

**Inspection Photos**  
**Location Name: Chaplin Danford #44-32**  
**Location ID:320609**



**Photo 1 PH and WH**

**Photo 2 stained soil remove from around PU**

Inspection Photos  
Location Name: Chaplin Danford #44-32  
Location ID:320609



Colorado Oil and Gas Conservation Commission  
39.82838, -104.56669, 1614.8m  
Mar 12, 2019 14:42:32

**Photo 3 Hatch on H2O tank has been installed**