

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2019

Submitted Date:

03/06/2019

Document Number:

687903842**FIELD INSPECTION FORM**Loc ID 326060 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215798	WELL	PR	09/18/1990	GW	067-07403	BONDAD 33-10 COM 104	PR

General Comment:[Downloadable photos at the end of this inspection report.](#)

Location**Lease Road:**

Type	Access		
comment:	Gravel entrance off county road.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Framed metal sign leaned up backwards against wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact information is not legible on sign.		
Corrective Action:	Please comply with Rule 210.e.		Date: 04/05/2019

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused vent stack and level controller equipment laying out on the ground.		
Corrective Action:	Please comply with rule 603.f.		Date: 04/05/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Seperator vent stack laying on ground.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		,
Comment:	Tank Labeling is faded and does not have a total capacity and missing emergency contact information.				
Corrective Action:	Please comply with Rule 210.d.				Date: 04/05/2019

Paint

Inspector Name: Stewart, Joseph

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 215798 Type: WELL API Number: 067-07403 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401963456	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754660
687903843	Sign with missing contact Information	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754634
687903844	Seperator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754635
687903845	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754636
687903847	Produced Water Tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754637
687903848	Missing Label Information	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754638