

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2019

Submitted Date:

03/06/2019

Document Number:

696100380

FIELD INSPECTION FORM

Loc ID 305922 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283713	WELL	SI	10/08/2018	OW	123-23684	KREYKES 13-15	TA

General Comment:

This is a WELL Inspection.
Well is TA.
Battery & ALL equipment is Shut-down.
Centralized Battery serves 5 Location IDs (305921, 305863, 305922, 306481, 306556).
Refer to FIR #696100376 and/or Location ID #305921 for Battery / Facility, Equipment info.

Follow-up to FIR #689300443 dated 12/01/2017.
1 of 1 Corrective Actions from previous FIR has been addressed.
1.) LTSI well had no MIT on record. Form 21 #401906743 indicates MIT done: 01/14/2019. (Approval Pending).
SI/TA well per variance Doc #401474555. (NOBLE).

2 - Corrective Actions identified on this FIR.
1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See photo #1.
Remove unused equipment at wellsite. Comply w/ Rule 603.f.
2.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.
Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).
UPDATE 03/07/2019: Corrective Action #2 removed due to current MIT on record. (Approval Pending).

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See photo #1.		
Corrective Action:	Remove unused equipment at wellsite. Comply w/ Rule 603.f.	Date:	04/05/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Refer to FIR #696100376 and/or Location ID #305921 for additional Fencing info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Equipment:			
Type:	#		corrective date
Comment:	Refer to FIR #696100376 and/or Location ID #305921 for additional Equipment info.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead w/ master valve, casing head & valves.		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.490481,-104.832546

Comment: [Centralized Battery serves 5 Location IDs \(305921, 305863, 305922, 306481,306556\). Refer to FIR #696100376 and/or Location ID #305921 for Tanks & Berms info.](#)

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 283713 Type: WELL API Number: 123-23684 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA. Well disconnected from flowline.
Form 4 #401920936 indicates TA since 11/30/2018. (Approval Pending).
LTSI well had no MIT on record from prev. FIR.
Form 21 #401906743 indicates MIT done: 01/14/2019. (Approval Pending).
SI/TA well per variance Doc #401474555. (NOBLE).
This addresses CA from prev. FIR.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
UPDATE 03/07/2019: Corrective Action #2 removed due to current MIT on record. (Approval Pending).	evinsb	03/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401962652	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754225
401964027	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755075
696100381	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754216