

# Construction and Stormwater Inspection

March 12, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 455456

Inspection Document #: 682404611

Weld County, CO

NWNE Section 18 T7N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 1.** Photo taken from the entrance of the location, facing Northwest. The track out issue has been resolved.



**Photo 2.** Photo taken from the northwestern location, facing East. Photo illustrates a ditch and berm BMP.



**Inspection Photos**  
**Location Name: EAST AULT 18-C PAD**  
**Location ID: 455456**



**Photo 3.** Photo taken from the northwestern location, facing South. Photo illustrates a berm BMP which has been installed along the western perimeter of the location. Berm BMP appears to be unconsolidated along portions of the location. An unconsolidated berm BMP is not a proper functioning BMP.



**Photo 4.** Photo taken from the southwestern location, facing East. Photo illustrates the topsoil stockpile. Also, the ditch BMP has topsoil which needs to be cleared out and the berm BMP needs to be re-installed, as it doesn't appear to be built to a sufficient height.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 5.** Photo taken along the southern location, facing East. See comments under Photo 4.



**Photo 6.** Photo taken from the southeastern location, facing North. Photo illustrates a ditch and berm BMP. Berm BMP needs to be re-installed, as it doesn't appear to be built to a sufficient height.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 7.** Photo taken along the eastern location, facing South. See comments under Photo 6.



**Photo 8.** Photo taken from the northeastern location, facing West. See comments under Photo 1.