

Inspection Photos

API: 05-073-06739

Operator: K3 OIL & GAS OPERATING COMPANY

Inspection Date: 3/11/2019

Inspection Photos



Photo 1. Facing north along the access road. Landowner road turns to the left. Pre-existing road goes north toward the location.

Inspection Photos



Photo 2. Facing north toward the location. The location is fenced. This area outside of the fence may need soil decompaction.

Inspection Photos



Photo 3. Facing north at the west side of the location. The soil has been recontoured and decompacted.

Inspection Photos



Photo 4. Facing northeast toward the location. The soil has been recontoured and decompacted.