

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2019

Submitted Date:

03/14/2019

Document Number:

687903965

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325759 _____ Stewart, Joseph _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215343	WELL	PR	12/21/1988	GW	067-06948	EVELYN PAYNE D 1	PR

General Comment:

[Location was covered in snow with a teardrop plowed around the wellhead during time of inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	Snowpacked single lane gravel road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed metal sign at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information is current. (970) 247-6916		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pump jack.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around seperator and meter house.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead with PVC bradenhead inspection port.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pig launcher on edge of location.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215343 Type: WELL API Number: 067-06948 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date: