


**PIT STATUS EVALUATION FORM**

Facility ID: 115128  
 Pit Name: MAPLE UPRR 2

Duplicate Record(s) Pit #



**Legend**

- Database Pit Location
- Producing Well
- + Shut In Well
- ⊕ Temp Aban Well
- ⊗ Abandoned Well
- ⊘ Dry & Aban Well
- ◆ Injection Well
- Other Well Status




Image Source:  
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: ROCK OIL CORP  
 T: 7S R: 63W Sec: 11 QQ: NENW 6th Meridian  
 Latitude: 39.460728 Longitude: -104.415503 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active**       Form 15: Pit Permit N/A      Assoc. Well Seq No(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_
- Closed**       Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
     Well API Seq # (s) DA# 06492 (8-19-1986)  
 Other documentation LIF# 447208 (8-1986)
- Abandoned**       Possible un-reclaimed pit(s) or adverse conditions, no closure docs       Site Visit  
 **Unknown**       No Site Visit  
 Add'l Review

Notes: No Form 15. LIF(1985) open & wet pits, LIF(1986) "good surface rehab; earthen dam + East for watering pond for cattle"