

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/18/2019

Submitted Date:

03/18/2019

Document Number:

675002030

FIELD INSPECTION FORM
 Loc ID 312464 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
Colby, Lou		lou.colby@state.co.us	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221691	WELL	SI	09/01/2017	GW	077-08293	USA 1-14 HC	TA

General Comment:

This is a follow up inspection to FIR Doc#675203563 dated 11-8-2016 and 675001753 dated 1/16/19
 Any corrective actions not addressed from previous inspections are still applicable.
 Unmarked risers and deadmen put people at risk in this area.
 No corrective actions have been done.

Location				
Lease Road:				
Type	Access			
comment:	No maintenance done at this time			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/ 970/858/8550			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unmarked risers and deadmen. meter run			
Corrective Action:	Comply with Rule 603.f .			Date: 04/15/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	#			corrective date
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 221691 Type: WELL API Number: 077-08293 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment:

Equipment unhooked
No production on file. No MIT on file. Listed as corrective action on Previous inspection
Doc#675201663

Corrective Action: Contact COGCC Engineer if over 5 year date or Fails MIT

Date: 11/21/2016

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002031	Inspection 675002030 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4767231