

Inspection Photos
Operator: BP America
Location/API #: 067-05144
Date: 2-18-2019



Photo 1. View of the northern project area from the northern edge of the driving surface facing eastward. An erosional channel that is approximately 2-4 feet wide and 2 feet deep is eroding the northern project area.



Photo 2. View of the eastern project area from the northeastern project area facing southward. Little to no vegetation observed. Erosion is occurring across the bare soil surface.



Photo 3. View of unmarked rig anchor within the northern project area.



Photo 4. View of the western project area from the northwestern corner facing southward. Little desirable vegetation present here.



Photo 5. View of cable debris that appears to be exposed by erosion.



Photo 6. View of cable debris within the western project area.



Photo 7. View of erosion occurring along the access road and onto the project area within the southeastern project area.