

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2019

Submitted Date:

03/19/2019

Document Number:

687904074**FIELD INSPECTION FORM**
 Loc ID 311972 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285747	WELL	PR	08/31/2016	GW	067-09204	JAMES A 1	PR
285749	WELL	PR	07/19/2006	GW	067-09205	JAMES A 3	PR
412008	WELL	PR	09/29/2010	GW	067-09730	JAMES A 5	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Gravel driveway through locked gate and across private property.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Framed metal signs at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information is posted on all 3 signs. (970) 247-6916			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire fence.			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Cattle panels around pumpjacks and wellheads.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separators and produced water tanks.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 3			corrective date
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Wellheads with PVC bradenhead inspection ports.			
Corrective Action:				Date:
Type: Pump Jack	# 3			
Comment:				
Corrective Action:				Date:

Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	PBV STEEL		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285747	Type:	WELL	API Number:	067-09204	Status:	PR	Insp. Status:	PR
Facility ID:	285749	Type:	WELL	API Number:	067-09205	Status:	PR	Insp. Status:	PR
Facility ID:	412008	Type:	WELL	API Number:	067-09730	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMP's seem to be working correctly. Location is dry and is graded well. This location did not have any silt fence or waddles.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT