

**Inspection Photos**  
**Location Name: Adam George GU1**  
**Location ID: 318150**



**Pic 1**

**Pic 2**

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 3



Pic 4

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 5



Pic 6 Possible leak

**Inspection Photos**  
**Location Name: Adam George GU1**  
**Location ID: 318150**



**Pic 7**

**Pic 8**

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 9. Possible leak on lubricator cap.

Pic 10

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 11

Pic 12

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 13

Pic 14

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



COLORADO OIL AND GAS CONSERVATION COMMISSION  
40.17161, -105.00454, 4829.8ft, 274°  
03/18/2019 09:19:55

Pic 15



COLORADO OIL AND GAS CONSERVATION COMMISSION  
40.17171, -105.00474, 4827.5ft, 12°  
03/18/2019 09:23:05

Pic 16

Inspection Photos  
Location Name: Adam George GU1  
Location ID: 318150



Pic 17



Pic 18

**Inspection Photos**  
**Location Name: Adam George GU1**  
**Location ID: 318150**



**Lease Road Entrance. Pic 19**