

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/19/2019

Submitted Date:

03/19/2019

Document Number:

685100663

**FIELD INSPECTION FORM**
 Loc ID 336222 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@Anadarko.com	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240807	WELL	PR	12/01/2018	GW	123-08595	TOM RUSSELL 'D' 1	PR
260497	WELL	SI	03/01/2017	OW	123-20497	HSR-RUSSELL 15-25A	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: [Fencing around wellhead.](#)

Corrective Action:

Date:

Type WELLHEAD

Comment: [Fencing around pump jack and wellhead.](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Other

#

Comment: [Bradenhead plumbed to surface.](#)

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Other

#

Comment: [Bradenhead plumbed to surface](#)

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240807	Type:	WELL	API Number:	123-08595	Status:	PR	Insp. Status:	PR
Facility ID:	260497	Type:	WELL	API Number:	123-20497	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Wells on location appear to be producing.								
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Arrived on location at approx 1115. At time of inspection location appears to be in compliance with COGCC rules.	medinaj	03/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100664	Location Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4767705">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4767705</a>