

Interim Reclamation Inspection

March 15, 2019

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 428225

Inspection Document #: 682404668

Weld County, CO

NWSW Section 5 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 1. Photo taken from the northeastern well pad, facing South. Operator has failed to perform interim reclamation per Rule 1003.b. to reduce disturbance areas only reasonably needed for production operations.



Photo 2. Photo taken from the northeastern well pad, facing West. See comments under Photo 1.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 3. Photo taken from the northeastern well pad, facing South. See comments under Photo 1.



Photo 4. Photo taken from the northeastern well pad, facing West. See comments under Photo 1.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 5. Photo taken from the well pad, facing South. Operator has failed to remove equipment from the previous inspection.



Photo 6. Photo taken from the wellhead, facing East. Appears the Operator has cleaned stained soil around the wellhead but has failed to remove the unused riser and stained soil was observed at the base of the pumpjack.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 7. Photo taken from the flare, facing North. Operator has failed to inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Also, unused riser observed.



Photo 8. Photo taken from the engine. See comments under Photo 7.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 9. Photo taken from the loadout. See comments under Photo 7.



Photo 10. Photo taken from the production tanks, facing East. Operator has failed to perform the previous corrective action. No capacities on production tanks.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 11. Photo taken from the produced water tank, facing East. Operator has failed to perform the previous corrective action. No safety placarding.