

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2019

Submitted Date:

03/20/2019

Document Number:

687904134

FIELD INSPECTION FORM

Loc ID 333870 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264750	WELL	IJ	04/01/2018	DSPW	067-08758	BARNES WTR DISP WELL (EPA) 1	IJ
269138	WELL	PR	08/20/2003	GW	067-08860	JOHN BARNES A 2	PR

General Comment:

[Facility inspection of above ground equipment. Downloadable photo at end of inspection report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Well maintained gravel road with multiple gates through private property.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed metal signs at entrance to location.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels with NFPA, contents and volume clearly marked on all tanks.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Safety signs posted at doors to all buildings.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on framed metal signs at entrance as well as on doors to entrances of buildings. (970) 247-6916/911		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around entire facility.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around separator.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panels around wellheads.		
Corrective Action:			Date:
Equipment:			
Type: Other	#		corrective date
Comment:	Injection well building, Injection pump building, valve control building, Motor control center building (MCC)		
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	Wellheads.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:	2 on 750 BBL tanks, 1 on Separator.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:	Carsonite markers on ground at deadmen from plowing snow.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		,
Comment:	Produced water tanks are 750 BBL each. Thief hatch on T-1427-1 is open.				
Corrective Action:	comply with Rule 605.d.				Date: 03/27/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Concrete	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 264750 Type: WELL API Number: 067-08758 Status: IJ Insp. Status: IJ

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 269138 Type: WELL API Number: 067-08860 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
Berms	Pass					Berm around location Perimeter.
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [10 BBL fiberglass tank with sufficient secondary containment outside of injection well building.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904135	Thief hatch.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769094