

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2019

Submitted Date:

03/20/2019

Document Number:

687904137**FIELD INSPECTION FORM**Loc ID 306790 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265094	WELL	PR	08/15/2004	GW	067-08766	ZELLITTI 34-9 34-1	PR
417633	WELL	PR	11/02/2010	GW	067-09817	ZELLITTI 34-9 34-3	PR

General Comment:[Downloadable photos at end of inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel two track road into location.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Framed metal sign at entrance of location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Current emergency contact information. (505) 324-5170			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Pump jack engine exhaust flexible hose has come loose and laying on the ground.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Other	# 1			
Comment:	Pigging station on edge of location.			
Corrective Action:				Date:
Type: Pump Jack	# 2			
Comment:	Stuffing box leaking produced water and staining gravel around wellhead			
Corrective Action:	Comply with Rule 605.d.			Date: 03/22/2019
Type: Ancillary equipment	# 2			
Comment:	wellheads with PVC bradenhead access port.			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	265094	Type:	WELL	API Number:	067-08766	Status:	PR	Insp. Status:	PR
Facility ID:	417633	Type:	WELL	API Number:	067-09817	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904138	packing leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769095