

# Interim Reclamation and Stormwater Inspection

March 5, 2019

Operator: SRC ENERGY INC - 10311

Location ID: 436152

Inspection Document #: 674902643

Weld County, CO

NESE Section 32 T1N R66W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 1.** Photo taken from the eastern perimeter of the location, facing Northwest. Appears the Operator has not performed interim reclamation activities to reduce disturbance areas only needed for production operations at the location.



**Photo 2.** Photo taken from access road looking into the location, facing West. See comments from Photo 1.

Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 3.** Photo taken from the location, facing West. See comments from Photo 1.



**Photo 4.** Photo taken from the northwestern perimeter of the location, facing North. Appears the Operator installed sediment trap with a temporary stabilized outlet.



Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 5.** Photo taken from the location, facing East. See comments from Photo 4. At the time of this inspection, it appears the Operator has installed sufficient stormwater and erosion control BMPs in accordance to Rule 1002.f. standards.



**Photo 6.** Photo taken from the northwestern perimeter of the location, facing North. See comments from Photo 1.

Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 7.** Photo taken from the northeastern perimeter of the location, facing East. Appears land owner potentially is storing equipment on location.



**Photo 8.** Photo taken from the northern perimeter of the location, facing South. See comments from Photo 7.

Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 9.** Photo taken from the eastern perimeter of the location, facing South. See comments from Photo 1.



**Photo 10.** Photo taken from the eastern perimeter of the location, facing North. See comments from Photo 1



Inspection Photos  
Location Name: SRC ENERGY INC/1N66W32  
Location ID: 436152



**Photo 11.** Photo taken from the eastern perimeter of the location, facing West. See comments from Photo 1.



**Photo 12.** Aerial imagery showing the current 5.35 acre disturbance area in the blue polygon. The approved 2A stated a disturbance area of 4.8 acres during construction and 1.6 acres after interim reclamation, which should have been completed by 1/28/2018 (6 months after production of the last well on location which was 7/28/2017).