

Inspection Photos

API: 05-071-06396

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 3/20/2019

Inspection Photos



Photo 1. Facing toward the beginning of the reclaimed access road. Rock rip/rap has been placed in the drainage channel for erosion control.

Inspection Photos



Photo 2. Facing west along the reclaimed access road.

Inspection Photos



Photo 3. There is vegetation beginning to establish an areas along the road.

Inspection Photos



Photo 4. Facing southwest along the steep grade of the reclaimed road.

Inspection Photos



Photo 5. Facing northwest toward the GE-73-94 location from a distance.

Inspection Photos



Photo 6. Facing southeast toward the GE-70-93 and GE-68-93 locations from a distance.