

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-06663
Date: 2-18-2019



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern project area from the southwestern edge facing eastward. Little desirable vegetation on fill slopes.



Photo 3. View of unmarked rig anchor within the project area.



Photo 4. View black plastic debris and erosion within the northeastern project area.



Photo 5. View of debris within the northwestern project area.