

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2019

Submitted Date:

03/25/2019

Document Number:

690101124

**FIELD INSPECTION FORM**

Loc ID 320492 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1001 17TH STREET #2000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266722	WELL	PA	11/24/2018	GW	001-09465	EQUINOX 15-9	EG
463366	SPILL OR RELEASE	AC	03/18/2019		-	Equinox 9-9 & 15-9	EG

**General Comment:**

Engineering integrity inspection performed on March 20th, 2019 in response to initial form 19 spill report Doc #401970954 received by COGCC on 03/15/2019 that outlines: Potential soil and groundwater impacts were discovered at the tank battery during abandonment activities. Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

**Inspected Facilities**

Facility ID: 266722 Type: WELL API Number: 001-09465 Status: PA Insp. Status: EG

**Flowline**

#1	Type:	of Lines	
----	-------	----------	--

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: No flowline risers observed on location/ (PA) wellhead.  
 Note: COGCC Rule 1105.d. (as applicable) Within 30 days of an operator completing abandonment requirements for an off-location flowline or crude oil transfer line the operator must submit a Flowline Report, Form 44, to the Director. If the operator abandons an off-location flowline and has not submitted latitude and longitude for the flowline??s risers, the Flowline Report, Form 44, must include this information.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 463366 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**COGCC Comments**

Comment	User	Date
Note: There is (1) disconnected/ out of service gas gathering riser and meter run on location:  The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.	maclarej	03/25/2019
Well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #401846307 received on 11/20/2018. The equipment at facility/ battery is in process of being removed. Excavation and remediation activities in regard to historical impacts identified at the tank battery are in progress.	maclarej	03/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101129	Signage at access road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772251</a>
690101130	View of location (looking west)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772252">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772252</a>

690101131	Gas meter run (out of service)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772253</a>
-----------	--------------------------------	---