

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-06266
Date: 2-18-2019



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the northwestern project area from the eastern corner facing northeastward. Grey vegetation on well pad is comprised of annual weeds such as kochia (*Kochia scoparia*).



Photo 3. View of area in southwestern project area where there is no vegetation down-slope from the well pad. Aerial imagery indicates there may be a historic release in this area.



Photo 4. View of the western project area from the southern corner facing northwestward. What appears to be surface owner equipment is stored on the location.



Photo 5. View of the eastern project area from the southern corner facing northeastward.