

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2019

Submitted Date:

03/25/2019

Document Number:

690101136

FIELD INSPECTION FORM

Loc ID: 323181 Inspector Name: Maclaren, Joe On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
 Name of Operator: PDC ENERGY INC
 Address: 1775 SHERMAN STREET - STE 3000
 City: DENVER State: CO Zip: 80203

Findings:

4 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspection@pdce.com	
Porter, Phillip		phillip.porter@pdce.com	
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244879	WELL	SI	07/01/2018	OW	123-12674	WILKEN 15-6	EG
463212	OFF-LOCATION FLOWLINE	AC	03/12/2019		-	Wellhead Line 6SWSE	EG
463397	SPILL OR RELEASE	AC	03/21/2019		-	Wilkin 15-6	EG

General Comment:

Engineering integrity inspection performed on March 21st, 2019 in response to initial form 19 spill report Doc #401978548 received by COGCC on 03/20/2019 that outlines: A historical spill was observed while abandoning the production facility. The historic spill was observed at the separator. Spill mitigation efforts are underway. Details of observations made during this field inspection are located in the flowline section of this report. Photos uploaded.

Inspected Facilities

Facility ID: 244879 Type: WELL API Number: 123-12674 Status: SI Insp. Status: EG

Flowline

#1	Type:	of Lines	
----	-------	----------	--

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Inspector met with PDC Energy contract personnel (Tasman) on location. Flowlines have been removed, no risers observed. Well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #401919019 received on 01/25/2019. All tanks and equipment at facility/ battery are being removed. Excavation and remediation activities pertaining to historical impacts identified at the horizontal separator (removed) are in progress.

Corrective Action: _____ Date: _____

Facility ID: 463212 Type: OFF- API Number: - Status: AC Insp. Status: EG

Facility ID: 463397 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
*Note: There is (1) disconnected/ out of service gas gathering riser and meter run on location: The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.	maclarej	03/25/2019
*Note: COGCC Rule 1105.d. Within 30 days of an operator completing abandonment requirements for an off-location flowline or crude oil transfer line the operator must submit a Flowline Report, Form 44, to the Director. If the operator abandons an off-location flowline and has not submitted latitude and longitude for the flowline risers, the Flowline Report, Form 44, must include this information.	maclarej	03/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101138	Excavation/ remediation area (view east)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772962

690101139	Flowlines (dump) removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772963
690101140	Separator (out of service/ to be removed/ view N)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772964
690101141	Signage, meter run (out of service) & excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772965