

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2019

Submitted Date:

03/25/2019

Document Number:

687904202

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325770 _____ Stewart, Joseph _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215357	WELL	PR	06/11/2015	GW	067-06962	ROBERT DULIN 1	PR

General Comment:

Location				
Lease Road:				
	Type	Access		
	comment:	Gravel road access right off county road.		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Framed metal sign at entrance to location.		
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	<input type="text" value="(970) 247-6916/911"/>		
	Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	LOCATION		
	Comment:	barbed wire fence around location.		
	Corrective Action:			Date:
	Type	SEPARATOR		
	Comment:	Cattle panels around separator and meter house.		
	Corrective Action:			Date:
	Type	WELLHEAD		
	Comment:	Cattle panels around wellhead.		
	Corrective Action:			Date:
Equipment:				
Type: Gas Meter Run		# 1		corrective date
	Comment:			
	Corrective Action:			Date:
Type: Ancillary equipment		# 1		
	Comment:	Wellhead with PVC bradenhead access.		
	Corrective Action:			Date:
Type: Vertical Heated Separator		# 1		
	Comment:			
	Corrective Action:			Date:

Type: Bird Protectors	# 1	
Comment:	On separator stack.	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 215357 Type: WELL API Number: 067-06962 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT