

Inspected Facilities

Facility ID: 456260 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Completion

Operation: Preparation

Date Flowback:

Contractor: n/a

Comment: Location awaiting flowback completion.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>On Monday 3/25/19, I Adam Kraich performed an inspection of the Merlin Pad, owned and operated by Extraction Oil & Gas. While on inspection, I observed sound wall infrastructure on location, as well as waste management infrastructure (portable restrooms and dumpster). The location appears to be awaiting flowback operations. Wellheads are not built for production at time of inspection. END.</p>	kraicha	03/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400116	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773189