

Inspection Photos

Operator: Rim Operating
Location/API #: 067-09333
Date: 2-18-2019



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern edge facing westward. Revegetation appears to be progressing, but appears sparse in portions and needs monitoring.



Photo 3. View of erosional channels and failed wattles within the eastern project area.



Photo 4. View of more erosional channels showing failed wattles and sediment deposition offsite, within the southern project area.