

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2019

Submitted Date:

03/25/2019

Document Number:

688401616**FIELD INSPECTION FORM**

Loc ID 335644 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
,		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283679	WELL	SI	09/01/2018	GW	123-23664	Graeber 31-33D	PA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:						
Corrective Action:						Date:

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	WH has what appears to be a VOC leak around the hammer nut cap on WH.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 03/23/2019

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☒ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.005303 Long: 105.000880Wind: None Speed: (mph) Direction From: Weather: Mostly Temperature: (F)Assisting Staff: Jason Gomez Camera #: ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1015	AM	1025	AM	Wellhead(s)

Comment: Detected what appears to be a VOC leak around top cap of WHCorrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.Date: 03/23/2019**COGCC Comments**

Comment	User	Date
<u>This is a follow up inspection per Doc#685100699. Returned to location to perform a flirr camer video. Upon performing flirr video found what appeared to a VOC leak around Top cap on WH. Contact COGCC engineering Diana Burn. Diana Burn indicated that Extraction oil and gas was going to return to location and repair issues with well.</u>	<u>silverr</u>	<u>03/25/2019</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401617	video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773464